

# VEHICLE INSPECTION REPORT

**RV55AMK**

## SUZUKI JIMNY 1.3 VVT JLX 3dr

### Inspection

### Vehicle

VAT	Margin
V5	Present

### Details

<b>Reg. date</b>	18/11/2005	<b>Body Style</b>	Estate	<b>Body / Panel Wrap</b>	No Wrap
<b>Year</b>	2005	<b>Keys</b>	1	<b>GVW</b>	1420kg
<b>Mileage</b>	70,654 Miles Not Warranted	<b>Service history</b>	Yes	<b>Gearbox</b>	MANUAL
<b>Fuel Type</b>	Petrol	<b>Service documents</b>	Service Book	<b>Gears</b>	5
<b>Colour</b>	SILVER	<b>Number of stamps</b>	5		
<b>VIN</b>	JSAFJB43V00207389	<b>MOT Due</b>	20/11/2026		

### 5 SERVICE STAMPS

### Tyres

NSF
NSR
OSF
OSR
Spare

### Photos

