

# VEHICLE INSPECTION REPORT

**FN64UFE**

## FIAT SCUDO 10Q 1.6 Multijet 90 H1 Comfort Van

Inspection	Vehicle	
	VAT	Margin
	V5	Present

### Details

<b>Reg. date</b>	30/12/2014	<b>Keys</b>	1	<b>Gearbox</b>	MANUAL
<b>Year</b>	2014	<b>MOT Due</b>	19/11/2026	<b>Gears</b>	5
<b>Mileage</b>	96,829 Miles Warranted	<b>CAP Clean</b>	£1,750.00	<b>Length</b>	4.81m
<b>Fuel Type</b>	Diesel	<b>CAP Average</b>	£1,375.00	<b>Width</b>	1.90m
<b>Colour</b>	WHITE	<b>CAP Below</b>	£975.00	<b>Height</b>	1.89m
<b>VIN</b>	ZFA27000064345511	<b>Body / Panel Wrap</b>	No Wrap		
<b>Body Style</b>	Panel Van	<b>GVW</b>	2661kg		

<b>Tyres</b>	
<b>NSF</b>	
<b>NSR</b>	
<b>OSF</b>	
<b>OSR</b>	
<b>Spare</b>	