

# VEHICLE INSPECTION REPORT

**RK10XCZ**

## VOLKSWAGEN GOLF 1.6 TDI 105 SE 5dr

### Inspection

### Vehicle

VAT	Margin
V5	Present

### Details

<b>Reg. date</b>	01/03/2010	<b>Keys</b>	2	<b>CAP Below</b>	£150.00
<b>Year</b>	2010	<b>Service history</b>	Yes	<b>Body / Panel Wrap</b>	No Wrap
<b>Mileage</b>	164,551 Miles Warranted	<b>Service documents</b>	Service Book	<b>GVW</b>	1980kg
<b>Fuel Type</b>	Diesel	<b>Number of stamps</b>	14	<b>Gearbox</b>	MANUAL
<b>Colour</b>	BLUE	<b>MOT Due</b>	01/03/2027	<b>Gears</b>	5
<b>VIN</b>	WVWZZZ1KZAM610602	<b>CAP Clean</b>	£760.00		
<b>Body Style</b>	Estate	<b>CAP Average</b>	£360.00		

Invoices, 14 Service Stamps

### Tyres

NSF
NSR
OSF
OSR
Spare

### Photos

