

# VEHICLE INSPECTION REPORT

**PK06ODM**

## HONDA JAZZ 1.2 i-DSI S 5dr

Cat: N

### Inspection

### Vehicle

VAT	Margin
V5	Present

### Details

<b>Reg. date</b>	31/03/2006	<b>Body Style</b>	Hatchback	<b>Body / Panel Wrap</b>	No Wrap
<b>Year</b>	2006	<b>Keys</b>	1	<b>GVW</b>	1490kg
<b>Mileage</b>	87,422 Miles Not Warranted	<b>MOT Due</b>	28/01/2027	<b>Gearbox</b>	MANUAL
<b>Fuel Type</b>	Petrol	<b>CAP Clean</b>	£350.00	<b>Gears</b>	5
<b>Colour</b>	SILVER	<b>CAP Average</b>	£150.00	<b>Doors</b>	5
<b>VIN</b>	JHMGD57106S203325	<b>CAP Below</b>	£150.00		

Category N Insurance Loss. No Structural Damage and Repairable - Insurer Decided Not to Repair.

### Tyres

NSF
NSR
OSF
OSR
Spare

### Photos

