

VEHICLE INSPECTION REPORT

KM12HDL

PEUGEOT 107 1.0 Active 5dr

Inspection

Vehicle

| | |
|-----|---------|
| VAT | Margin |
| V5 | Present |

Details

| | | | | | |
|------------|---------------------------|-------------------|--------------|-------------------|---------|
| Reg. date | 24/05/2012 | Keys | 3 | CAP Below | £150.00 |
| Year | 2012 | Service history | Yes | Body / Panel Wrap | No Wrap |
| Mileage | 95,600 Miles Warranted | Service documents | Service Book | GVW | 1190kg |
| Fuel Type | Petrol | Number of stamps | 3 | Gearbox | MANUAL |
| Colour | MAUVE/PURPLE | MOT Due | 05/11/2026 | Gears | 5 |
| VIN | VF3PNCFB488662558 | CAP Clean | £850.00 | Doors | 5 |
| Body Style | Hatchback | CAP Average | £450.00 | | |

3 SERVICE STAMPS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos

