

VEHICLE INSPECTION REPORT

MT18VPA

HYUNDAI TUCSON 1.6 GDi Blue Drive SE Nav 5dr 2WD

Inspection

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	09/05/2018	Keys	1	CAP Below	£4,450.00
Year	2018	Service history	Yes	Body / Panel Wrap	No Wrap
Mileage	79,163 Miles Not Warranted	Service documents	Service Book	GVW	1895kg
Fuel Type	Petrol	Number of stamps	9	Gearbox	MANUAL
Colour	GREY	MOT Due	Expired	Gears	6
VIN	TMAJ3811LJJ651531	CAP Clean	£5,900.00		
Body Style	Estate	CAP Average	£5,150.00		

9 SERVICE STAMPS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos

