

VEHICLE INSPECTION REPORT

SL04WFH

VOLKSWAGEN POLO 1.2 S 55 3dr [AC]

Cat: C

Inspection Vehicle

VAT	Margin
V5	Present

Details

Reg. date	26/03/2004	Body Style	Hatchback	Body / Panel Wrap	No Wrap
Year	2004	Keys	2	GVW	1560kg
Mileage	154,830 Miles Warranted	Service history	Yes	Gearbox	MANUAL
		Service documents	Service Book	Gears	5
Fuel Type	Petrol	Number of stamps	8	Doors	3
Colour	SILVER	MOT Due	29/05/2026		
VIN	\/\\\/\7779N74Y164938				

Category D Insurance Loss. Vehicle Damaged But Repairable - Insurer Decided Not To Repair. Category C Insurance Loss. Vehicle Extensively Damaged But Repairable -Insurer Decided Not To Repair. 8 SERVICE STAMPS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





